

**WORK SURFACES USED IN RODENT
PROCEDURES MUST BE EASILY
DECONTAMINATED/SANITIZED OR
COVERED BY IMPERVIOUS, DISPOSABLE
DRAPES.**

**CORK BOARDS/STYROFOAM MAY ONLY BE
USED FOR NECROPSY/NON-SURVIVAL
PROCEDURES AND ONLY WHEN COVERED
WITH A CLEAN, IMPERVIOUS, DISPOSABLE
DRAPE**

SC #162.1
Eff. 3/17